# NVRsolo Release Note

## Release Version 2.0.1 (2014/9/16)

## Modules

| Item | | | Version |
|---|---|---|---|
| **FW** | NVR | NS-1040 | 02.00.0001.0004 |
| | | NS-1080 | |
| | | NS-2040 | |
| | | NS-2080 | |
| | | NS-8060 | |
| | | NS-8065 | |
| | | NS-2160 | 02.00.0001.0006 |
| | | NS-8160 | |
| | | NS-8165 | |
| | Camera Package | | DP v3.4 |
| **Application** | Install Wizard | | 2.0.1 |
| | Remote Live Viewer | | 2.0.1 |
| | Playback System | | 2.0.1 |
| | Backup System | | 2.0.1 |
| | Verification Tool | | 2.0.1 |
| | Offline License Tool | | 2.0.1 |
| **Document** | Local User manual | | 2.0.1 |
| | Remote User manual | | 2.0.1 |
| | QSG | | 2.0.1 |

## Bug Fixed
1. Fix fisheye dewarp issue
2. Fix issue for specific camera's display status

## Known Issues
1. Some functions may not work properly on Internet Explorer 11. Internet Explorer 8, 9, 10, Windows Chrome or Mac Safari v7.0 is recommended. IE11 will be officially supported in the coming version.
2. Unable to adjust audio volume on HDMI monitor. It will be fixed in later version.
3. V1.1.2 is the minimum version for upgrade to v2.0. Please upgrade to v1.1.2 before upgrade to v2.0.
4. NS-8065 does not support disk hot swap on some external storages (eSATA DAS) currently. The RAID status maybe incorrect. Please reboot NVRsolo after installation, or install the external storage while NVRsolo is off. It will be fixed in later version.


**Please find DP 3.4 release note for camera integration, bug fixed and known issue.**

**Warning: Please be noted that once upgraded to 2.0.1, the firmware cannot be downgraded.**

**www.nuuo.com**