Sony



Spark
UltraHD technology

: not avaliable on camera

*1: not avaliable on software

*2: not test on software

For multi stream support:

Yes: multi stream fix to 500kbps/100kbps Yes*: multi stream setting support in Crystal

For PTZ:

Yes*: Joystick support to control PTZ speed in Crystal

Device Name	Tested Firmware	Video Format	Video Ch	Max Resolution	Audio	I/O Ch	PTZ	On-Edge Motion	UPnP	Camera Search Tool	Multi Stream Support	Remarks
SR-C- F21100	2.420.0005.0 .R	H.264 MJPEG	1	1920x1080	1-way	1/1	Yes	Yes	Yes	-	Yes*	
Note:	 Camera Search and Auto Detect was not supported. (Camera firmware issue) Bitrate Range in camera web was not sync with NUUO server. (Camera firmware issue) G711A 16K was not supported. (NUUO server limitation) Because of bitrate range was not sync between server and camera web, camera setting probably fail. (Camera firmware issue) 											
SR-C- F25100-V	2.210.0004.0 .T.A.3013.3N .NR	H.264 MJPEG	1	1920×1080	1-way	2/1	Yes	Yes	Yes	-	Yes*	
Note:	1. Camera Search and Auto Detect was not supported. (Camera firmware issue) 2. Bitrate Range in camera web was not sync with NUUO server. (Camera firmware issue) 3. G711A 16K was not supported. (NUUO server limitation) 4. Because of bitrate range was not sync between server and camera web, camera setting probably fail. (Camera firmware issue)											
SR-C- F24110-FV	2.420.0005.0 .R	H.264 MJPEG	1	1920×1080	1-way	1/1	Yes*	Yes	Yes	-	Yes*	
Note:	 Camera Search and Auto Detect was not supported. (Camera firmware issue) Bitrate Range in camera web was not sync with NUUO server. (Camera firmware issue) In G.711 sound will distort. (Camera firmware issue) Zoom can't use successfully. (Camera performance limitation) 											
SR-C- F26110	2.420.0005.0 .R	H.264 MJPEG	1	1920x1080	1-way	2/1	Yes	Yes	Yes	-	Yes*	
Note:	1. Camera Search and Auto Detect was not supported. (Camera firmware issue) 2. Bitrate Range in camera web was not sync with NUUO server. (Camera firmware issue) 3. G711A 16K was not supported. (NUUO server limitation) 4. Because of bitrate range was not sync between server and camera web, camera setting probably fail. (Camera firmware issue)											
SR-C- F22100-V	2.420.0005.0 .R	H.264 MJPEG	1	1920x1080	-	-	-	Yes	Yes	-	Yes*	
Note:	Camera Search and Auto Detect was not supported. (Camera firmware issue) Bitrate Range in camera web was not sync with NUUO server. (Camera firmware issue) Because of bitrate range was not sync between server and camera web, camera setting probably fail. (Camera firmware issue)											
SR-C- F23120-V	2.420.0005.0 .R	H.264 MJPEG	1	1920×1080	1-way	-	Yes*	Yes	Yes	-	Yse*	
Note:	1. Camera Sea 2. Bitrate Ran 3. G711A 16	arch and A ge in came (was not s bitrate rar	era web supporte	ect was not sup was not sync was not sync wed. (NUUO serv not sync betwo	vith NUU ver limita	JO serve ation)	er. (Can	nera firmwa	•	,	fail. (Cam	nera

Sony



Spark
UltraHD technology

: not avaliable on camera*1: not avaliable on software*2: not test on software

For multi stream support:

Yes: multi stream fix to 500kbps/100kbps Yes*: multi stream setting support in Crystal

For PTZ:

Yes*: Joystick support to control PTZ speed in Crystal

Device Name		 Video Ch	Max Resolution	Audio	I/O Ch	PTZ	On-Edge Motion				Remarks
INitida	01.10:01.08: 01.13:01.11: 01.05:00.04	1	1920x1080	-	-	-	-	-	-	Yes*	

Note: Second stream is unable to achieve setting bit rate.(Camera performance limitation)