

## Release Version 2.0.0 (2014/3/3)

### Modules

Item	Version	
<b>FW</b>	NVR	NS-1040
		NS-1080
		NS-8060
		NS-8065
	Camera Package	DP v3.1 03. 01.0000.0032
<b>Application</b>	Install Wizard	2.0.0
	Remote Live Viewer	2.0.0
	Playback System	2.0.0
	Backup System	2.0.0
	Verification Tool	2.0.0
	Offline License Tool	2.0.0
<b>Document</b>	Local User manual	2.0.0
	Remote User manual	2.0.0
	QSG	2.0.0

### New Features

1. Support camera multi-stream setting for saving remote bandwidth and local decoding loading<sup>1</sup>.
2. Support camera two-way audio<sup>2</sup>(Local and Internet Explore only).
3. New action supported<sup>3</sup>:
  - Camera snapshot to FTP.
  - E-mail with snapshot.
  - Send to CMS with snapshot.
4. Execute HDD S.M.A.R.T self-test on server. Monitor hard drives health easily.
5. Support A08 I/O Box.
6. Enhance event log: click and play (Local and Internet Explore only)
7. RAID 0, 1, 5, and 10 for maximum capacity or data protection on NS-8065.
8. Compatible with Windows Chrome and Mac safari v7.0.

### Bug Fixed

1. Fix the issue that when backup a video footage from local on USB drive, it overwrites the previous backup.
2. Fix the issue that transferring camera or POS license may pop up "error code: 268435468" in License Management page.
3. Fix the issue that camera DO duration configuration may not be saved under Japanese and Chinese menu.
4. Fix the issue about digital PTZ in live view and playback.
5. Other minor bugs.

### Known Issues

1. Some functions may not work properly on Internet Explorer 11. Internet Explorer 8, 9, 10, Windows Chrome or Mac Safari v7.0 is recommended. [IE11 will be officially supported in the coming version.](#)
2. Unable to adjust audio volume on HDMI monitor. It will be fixed in later version.
3. V1.1.2 is the minimum version for upgrade to v2.0. [Please upgrade to v1.1.2 before upgrade to v2.0.](#)

<sup>1</sup> DP 3.1 and above

<sup>2</sup> DP 3.1 and above

<sup>3</sup> DP 3.1 and above

4. NS-8065 does not support disk hot swap on some external storages (eSATA DAS) currently. The RAID status maybe incorrect. Please reboot NVRsolo after installation, or install the external storage while NVRsolo is off. [It will be fixed in later version.](#)

**Please find DP 3.1 release note for camera integration, bug fixed and known issue.**