

## Release Version v1.5.0 (2010/8/31)

### Modules:

Device Pack v 1.5.0

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & 3.3.11

### New Camera Supported:

**Brickcom:** CB-100A, CB-100Ae, FB-100A, FB-100Ae, FD-100Ae, WCB-100Ae, WFB-100Ae

**Fine:** CDV-3VM301, CDV-3VM501, CDV-3VWD960, CDV-3VWD960H, EP-601HW, EP-908HW, EP-936HW, EP-HTQ935, EP-Q2018H-IP, EP-Q2018HW-IP, EP-Q2026H-IP, EP-Q2026HW-IP, EP-Q2036H-IP, EP-Q2036HW-IP, MD-D1612, SP-PTIR737-IP, TCMA-99, TCMP-99, TCP-IPWD690, TCP-IPWD700DN, TCP-IRV540, TCP-IRV560/50M, TCP-MH802, TCP-VM201, TCP-VM501, WB-H811, WB-H814

**Hikvision:** DS-2CD702NF-E, DS-2CD702PF-E, DS-2CD712NF-E, DS-2CD712PF-E, DS-2CD732F-E, DS-2CD792NF-E, DS-2CD792PF-E, DS-2CD802N-IR1, DS-2CD802N-IR3, DS-2CD802N-IR5, DS-2CD802P-IR1, DS-2CD802P-IR3, DS-2CD802P-IR5, DS-2CD832F, DS-2CD832F-E, DS-2DF1-401H, DS-2DF1-402H, DS-2DF1-601H, DS-2DF1-602H, DS-2DF1-603H, DS-2DF1-604H, DS-2DF1-605H, DS-2DF1-606H, DS-2DF1-607H, DS-2DF1-611H, DS-2DF1-612H, DS-2DF1-613H, DS-2DF1-614H, DS-2DF1-615H, DS-2DF1-616H, DS-2DF1-617H, DS-2DM1-602H, DS-2DM1-603H, DS-2DM1-604H, DS-2DM1-612H, DS-2DM1-613H, DS-2DM1-614H, DS-6101HFI-SATA, DS-6104HCI, DS-6104HCI-SATA

**NetworkCamera:** GE-100-CB, GP-100-CB, WGE-100-CB, WGP-100-CB

**PELCO:** ID10, ID30, IDE20, IDS0, IE10, IE30, IEE10, IEE20, IES0, IMS0, IX30, IXE20, IXS0

**Sony:** SNC-RS44N, SNC-RS44P, SNC-RS46N, SNC-RS84N, SNC-RS84P, SNC-RS86N, SNC-RS86P, SNT-EP104, SNT-EX101

**Videosec:** IBF-211, ID-209, IDA-210, IP-206M, IS-240

### Note:

1. Bug fixed: SANYO-HD5600P can change resolution.
2. Onvif supported: AXIS\_P3301, Bosch\_NWC-0455

## Release Version v1.4.0 (2010/8/9)

### Modules:

Device Pack v 1.4.0

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & 3.3.11

### New Camera Supported:

**iCanTek:** iCanView362MP, iCanView332MP, iCanView350MP, iCanServer612

**SANTEC:** SNC-3901MDN, SNC-P3601M

## Release Version v1.3.0 (2010/7/21)

### Modules:

Device Pack v 1.3.0

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

### New Camera Supported:

**ACTi:** TCM-1511

**Arecont:** AV10005

**AXIS:** M1103, M1113, M1054, Q6034

**Panasonic:** BB-HCM547A, BB-HCM701

**SANTEC:** SNC-6201M, SNC-5211MIR

**Sony:** SNT-EX154, SNT-EX101E, SNT-EP154, SNC-CH140, SNC-DH140, SNC-CH180,  
SNC-CH240, SNC-DH240, SNC-RH164, SNC-RS46P

### Note:

1. Sony SNC-CH240, SNC-DH240 do not support resolution over 1920x1080

## Release Version v1.2.0 (2010/6/8)

### Modules:

Device Pack v 1.2.0

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

### New Features

1. Support Arecont I/O function

### New Camera Supported:

**ACTi:** ACM-3601, ACM-3603, ACM-3701, ACM-3703, ACM-4001  
TCD-2500, TCM-4101, TCM-5312, TCM-1231, TCM-1232  
TCM-5601, TCM-5611, TCM-3511, TCM-7411

**Arecont:** AV3135, AV1310, AV2110, AV3110, AV5110

**AXIS:** P1346, P5534, Q1910, Q1910-E, M1104, M1114  
M3203, M3203-V, M3204, M3204-V, P3304, M7001

**CNB:** IDC4000T, IVC4000T

**IQeye:** IQ040S, IQ041S, IQ042S, IQD30S, IQD31S  
IQD40S, IQD41S, IQD42S, IQ540S, IQ541S, IQ542S

**Panasonic:** BB-HCM100, BB-HCM110, BB-HCM580, BL-C140A

**Samsung:** SNB-2000, SNB-3000, SND-3080, SNV-3080

**Sanyo:** VCC-HD2500, VCC-HD2500P

**Sony:** SNT-EX104, SNC-DH180, SNC-RH124

**StarDot:** SDH500BN, SDH500B, SDH300B, SDH130BN, SDH130B  
SDH500VN, SDH500V, SDH300V, SDH130VN, SDH130V

### Bug Fixed:

2. Fixed MainConsole unexpected crash issue with Mobotix Q24M-sec camera.

## Release Version v1.1.1 (2010/5/12)

### Modules:

Device Pack v 1.1.1

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

### New Camera Supported:

**CNB:** IBE3815NVR, IBE3815PVR, IBE5810NCR, IBE5810PCR  
IDP4000VD, IDP4000VR, IDP4030VR, IGP1000, IGP1030  
IJB2000, INS2000, IPM3063N, IPM3063P, ISMC1063N, ISMC1063P  
ISS2765NW, ISS2765PW, IVP4000VR, IVP4030VR

**LevelOne:** FCS-7111

## Release Version v1.1.0 (2010/5/4)

### Modules:

Device Pack v 1.1.0

### Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

### New Camera Supported:

**ACTi:** AMU-9401, AMU-9711, TMU-9811, TMU-9911

**Bosch:** NW-455

**Brickcom:** WCB-100A, WFB-100A, FD-100A

**CISCO:** WVC210

**Dynacolor:** nNH221, nNH061, V1, V6

**Everfocus:** EAN-850A, EZN-850, EDN-800, EDN-850H, EAN900, EAN800AW, EAN800A  
EVS200A, EVS200AW, EPN2700, EPN3100, EPN3600

**LevelOne:** FCS-3031, FCS-3051, FCS-1131, FCS-1141, FCS-3071, FCS-0030, WCS-0030  
FCS-1121, FCS-3061, FCS-4020, FCS-1040 v3.0, WCS-2040 v3.0, FCS-1151

**MOBOTIX:** D24M-Basic, D24M-IT, D24M-Sec

**Panasonic:** BB-HCM705A, BB-HCM715A, BB-HCM735A

**Samsung:** SNP-3300A

**SanTec:** SNC-390DN/W, SNC-521IR/W, SNC-565IR/W, SNC-620/W, SNC-670ID/W

**Sanyo:** VCC-HD3500, VDC-HD3500, VDC-HD3500p, VCC-HD2100, VCC-HD2100P  
VCC-HD2300, VCC-HD2300P, VDC-HD3100, VDC-HD3100P  
VCC-HD3300, VDC-HD3300, VDC-HD3300P, VCC-HD4600, VCC-HD4600P  
VCC-HD5400, VCC-HD5400P, VCC-HD5600, VCC-HD5600P

**StarDot:** SD-130, SD-300, SD-500, SDEXP4, SDEXP2

**VIVOTEK:** IP8161, VS8102, FD8161, FD8361

### Notice:

1. Only compatible with NUUO MainConsole v3.3.0 above
2. Must install Main Console software before install device pack v1.1.0

