

Release Version v1.8.0 (2010/12/31)

Modules:

Device Pack v 1.8.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & v 3.3.12 & v 3.4

New Camera Supported:

ACTi: TCM7811,
Hikvision: DS-2CD7133-E, DS-2CD7153-E
Levelone: FCS-0040, FCS-3081, FCS-5051, FCS-5041, WCS-0040
Lilin: IPD112ESX, IPD552EX, IPR414ESX, IPR418ESX, IPR454, IPR458
Sony: SNC-CH110/B, SNC-CH110/S, SNC-CH220

Notice:

1. Bug fixed: Users can adjust Arecont camera's resolution by setting four video coordinate values.
(Not support Arecont 8000 series cameras.)

Release Version v1.7.0 (2010/11/12)

Modules:

Device Pack v 1.7.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & v 3.3.12 & v 3.4

New Camera Supported:

ACTi: ACM5811, ACM7511, TCD2100, TCM3001, TCM3011, TCM3401, TCM3411, TCM4201, TCM5001, TCM7011

ARM: MP13DDNWD, MP13VPDN

Camtron: IPH3611N, NVE1000A, NVE2000A, NVE4000A

CryptoTelecom: S-152

Dallmeier: DDZ40SM-HD

Panasonic: BL-C210, BL-C230, WJ-GXE500, WV-SF332, WV-SF335, WV-SF336, WV-SP302, WV-SP305, WV-SP306

Samsung: SNS-100

Sony: SNC-CH120, SNC-CH160, SNC-CH210/B, SNC-CH210/S, SNC-DH120, SNC-DH120T, SNC-DH140T, SNC-DH160, SNC-DH240T

Truen: TCAM-570

VIVOTEK: FD8133, FD8134, IP8132, IP8151, IP8330, IP8332, PZ7132, SD81X1

Notice:

1. Bug fixed: Panasonic WV-NP502 won't show error message when switching video codec to H.264.

Release Version v1.6.0 (2010/10/7)

Modules:

Device Pack v 1.6.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & v 3.3.12

New Camera Supported:

Arecont: AV2805

Camtron: CMNC-130, CMNC-200, CTNC-5358D, HLC-81A D/P, HLC-83V, HLC-83V/W
HLC-84V, HLC-84V/W

Honeywell: ACUIX, HCD554IP, HD3MDIP, HD4DIP, HD4MDIP, HNVE1

PELCO: IX10

Pixord: P600, P606, PB630, PD634, PL621, PV6901

SAE: ANNA 200M, E588HDE18C, E688HDE10

Notice:

1. Bug fixed: Fine WB-8211SDU can use PTZ function.

Release Version v1.5.0 (2010/8/31)

Modules:

Device Pack v 1.5.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & v3.3.11

New Camera Supported:

Brickcom: CB-100A, CB-100Ae, FB-100A, FB-100Ae, FD-100Ae, WCB-100Ae, WFB-100Ae

Fine: CDV-3VM301, CDV-3VM501, CDV-3VWD960, CDV-3VWD960H, EP-601HW, EP-908HW, EP-936HW, EP-HTQ935, EP-Q2018H-IP, EP-Q2018HW-IP, EP-Q2026H-IP, EP-Q2026HW-IP, EP-Q2036H-IP, EP-Q2036HW-IP, MD-D1612, SP-PTIR737-IP, TCMA-99, TCMP-99, TCP-IPWD690, TCP-IPWD700DN, TCP-IRV540, TCP-IRV560/50M, TCP-MH802, TCP-VM201, TCP-VM501, WB-H811, WB-H814

Hikvision: DS-2CD702NF-E, DS-2CD702PF-E, DS-2CD712NF-E, DS-2CD712PF-E, DS-2CD732F-E, DS-2CD792NF-E, DS-2CD792PF-E, DS-2CD802N-IR1, DS-2CD802N-IR3, DS-2CD802N-IR5, DS-2CD802P-IR1, DS-2CD802P-IR3, DS-2CD802P-IR5, DS-2CD832F, DS-2CD832F-E, DS-2DF1-401H, DS-2DF1-402H, DS-2DF1-601H, DS-2DF1-602H, DS-2DF1-603H, DS-2DF1-604H, DS-2DF1-605H, DS-2DF1-606H, DS-2DF1-607H, DS-2DF1-611H, DS-2DF1-612H, DS-2DF1-613H, DS-2DF1-614H, DS-2DF1-615H, DS-2DF1-616H, DS-2DF1-617H, DS-2DM1-602H, DS-2DM1-603H, DS-2DM1-604H, DS-2DM1-612H, DS-2DM1-613H, DS-2DM1-614H, DS-6101HFI-SATA, DS-6104HCI, DS-6104HCI-SATA

NetworkCamera: GE-100-CB, GP-100-CB, WGE-100-CB, WGP-100-CB

PELCO: ID10, ID30, IDE20, IDS0, IE10, IE30, IEE10, IEE20, IES0, IMS0, IX30, IXE20, IXS0

Sony: SNC-RS44N, SNC-RS44P, SNC-RS46N, SNC-RS84N, SNC-RS84P, SNC-RS86N, SNC-RS86P, SNT-EP104, SNT-EX101

Videosec: IBF-211, ID-209, IDA-210, IP-206M, IS-240

Notice:

1. Bug fixed: SANYO-HD5600P can change resolution.
2. Onvif supported: AXIS_P3301, Bosch_NWC-0455

Release Version v1.4.0 (2010/8/9)

Modules:

Device Pack v 1.4.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2 & v 3.3.11

New Camera Supported:

iCanTek: iCanView362MP, iCanView332MP, iCanView350MP, iCanServer612

SANTEC: SNC-3901MDN, SNC-P3601M

Release Version v1.3.0 (2010/7/21)

Modules:

Device Pack v 1.3.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

New Camera Supported:

ACTi: TCM-1511

Arecont: AV10005

AXIS: M1103, M1113, M1054, Q6034

Panasonic: BB-HCM547A, BB-HCM701

SANTEC: SNC-6201M, SNC-5211MIR

Sony: SNT-EX154, SNT-EX101E, SNT-EP154, SNC-CH140, SNC-DH140, SNC-CH180,
SNC-CH240, SNC-DH240, SNC-RH164, SNC-RS46P

Notice:

1. Sony SNC-CH240, SNC-DH240 do not support resolution over 1920x1080

Release Version v1.2.0 (2010/6/8)

Modules:

Device Pack v 1.2.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

New Features

1. Support Arecont I/O function

New Camera Supported:

ACTi: ACM-3601, ACM-3603, ACM-3701, ACM-3703, ACM-4001
TCD-2500, TCM-4101, TCM-5312, TCM-1231, TCM-1232
TCM-5601, TCM-5611, TCM-3511, TCM-7411

Arecont: AV3135, AV1310, AV2110, AV3110, AV5110

AXIS: P1346, P5534, Q1910, Q1910-E, M1104, M1114
M3203, M3203-V, M3204, M3204-V, P3304, M7001

CNB: IDC4000T, IVC4000T

IQeye: IQ040S, IQ041S, IQ042S, IQD30S, IQD31S
IQD40S, IQD41S, IQD42S, IQ540S, IQ541S, IQ542S

Panasonic: BB-HCM100, BB-HCM110, BB-HCM580, BL-C140A

Samsung: SNB-2000, SNB-3000, SND-3080, SNV-3080

Sanyo: VCC-HD2500, VCC-HD2500P

Sony: SNT-EX104, SNC-DH180, SNC-RH124

StarDot: SDH500BN, SDH500B, SDH300B, SDH130BN, SDH130B
SDH500VN, SDH500V, SDH300V, SDH130VN, SDH130V

Notice:

1. Bug Fixed: Fixed MainConsole unexpected crash issue with Mobotix Q24M-sec camera.

Release Version v1.1.1 (2010/5/12)

Modules:

Device Pack v 1.1.1

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

New Camera Supported:

CNB: IBE3815NVR, IBE3815PVR, IBE5810NCR, IBE5810PCR
IDP4000VD, IDP4000VR, IDP4030VR, IGP1000, IGP1030
IJB2000, INS2000, IPM3063N, IPM3063P, ISMC1063N, ISMC1063P
ISS2765NW, ISS2765PW, IVP4000VR, IVP4030VR

LevelOne: FCS-7111

Release Version v1.1.0 (2010/5/4)

Modules:

Device Pack v 1.1.0

Supported Systems:

MainConsole v 3.3.0 & v 3.3.2

New Camera Supported:

ACTi: AMU-9401, AMU-9711, TMU-9811, TMU-9911

Bosch: NW-455

Brickcom: WCB-100A, WFB-100A, FD-100A

CISCO: WVC210

Dynacolor: nNH221, nNH061, V1, V6

Everfocus: EAN-850A, EZN-850, EDN-800, EDN-850H, EAN900, EAN800AW, EAN800A
EVS200A, EVS200AW, EPN2700, EPN3100, EPN3600

LevelOne: FCS-3031, FCS-3051, FCS-1131, FCS-1141, FCS-3071, FCS-0030, WCS-0030
FCS-1121, FCS-3061, FCS-4020, FCS-1040 v3.0, WCS-2040 v3.0, FCS-1151

MOBOTIX: D24M-Basic, D24M-IT, D24M-Sec

Panasonic: BB-HCM705A, BB-HCM715A, BB-HCM735A

Samsung: SNP-3300A

SanTec: SNC-390DN/W, SNC-521IR/W, SNC-565IR/W, SNC-620/W, SNC-670ID/W

Sanyo: VCC-HD3500, VDC-HD3500, VDC-HD3500p, VCC-HD2100, VCC-HD2100P
VCC-HD2300, VCC-HD2300P, VDC-HD3100, VDC-HD3100P
VCC-HD3300, VDC-HD3300, VDC-HD3300P, VCC-HD4600, VCC-HD4600P
VCC-HD5400, VCC-HD5400P, VCC-HD5600, VCC-HD5600P

StarDot: SD-130, SD-300, SD-500, SDEXP4, SDEXP2

VIVOTEK: IP8161, VS8102, FD8161, FD8361

Notice:

1. Only compatible with NUUO MainConsole v3.3.0 above
2. Must install Main Console software before install device pack v1.1.0

